

IEQ SCHOOL DATA BASE

School Name: Reservoir High School

Principal: Patrick Saunderson

DATE: 1/23/2017

IEQ Team Leader: Adam Downes

IEQ System Leader: Greg Maciulla

LOOK-FORS	ROOM/LOCATION	COMMENTS	ADMIN	FACILITIES	WORK ORDER NUMBER of POTENTIAL IEQ	DATE ASSIGNED	COMPLETION DATE	30 DAY REVISIT	CLOSED
1. No unusual or offensive odors, or temperature discomfort	316, 325, 326A	Uncomfortable temperatures in the classrooms.		X	22036	2/23/2017			
2. No Air Fresheners	Office/Drnec, White/Staff BR, 227, 229/Science Planning, 337	Air fresheners, diffusers, and/or candles present in the designated areas.	X						
3. No food, dirty lunch boxes, etc. left in room	S-14/216, Staff BR/313 Closet, 321, 324, 329A, Planning	Food not in airtight containers.	X						
4. Vents are clean and unobstructed	100, Equip Storage, Instrument Repair, 102, 102 work room, CS 3, Auditorium Hall, Asst. Principal, Girl's LR, Office, Restroom, Women's BR, Wrestling, Athletic, Boys Locker Room/Work Room, Health Room, Guidance, Altshuler, Thurmon, Beil, Packman, 111, 112, 114, Kitchen, Kitchen BR, 109/203, 210, 211, Telecom Room, E5/Boys BR N.E., Fire, Sprinkler, Telcom Closet, 316, Staff BR, 320, 322, Boys BR, S-34, Girl's BR, 333, 335, Planning Room, S-31/Toilets by 337, E-6, Telecom 4, CS-8, S-34, E-8,	HVAC needs cleaning/Covered vents in 211 and 335/Exhaust needs cleaning	X						
5. Temperature sensors are not blocked	E-4/E-6, 303	Clutter and/or shelving units blocking the temperature sensors.	X						

IEQ SCHOOL DATA BASE

School Name: Reservoir High School

Principal: Patrick Sauderson

DATE: 1/23/2017

IEQ Team Leader: Adam Downes

IEQ System Leader: Greg Maciulla

<p>6. Area appears clean and dust free</p>	<p>100, 102, S-13, Ensemble Room, Hall Vending, 103, CS-3, Auditorium, Auditorium Hall, Control Room, Girls BR, Boys BR, Asst Principal, Concession Stand, Laundry, CS-5, Girls LR, Boys LR Shower, Gym Storage, Gym Bleachers, Gym Hallway, Training Room, Weights, 107, 108, Boys LR, Auxillary Gym, 106, Planning, Wrestling, Athletic Storage, E2, 108 Storage, Booster Closet/Staff Toilets, Health Room, Guidance, Bellamy/Finch, Drnec, Packman, Registrar, Flex, SGA, Atrium, 120, 118, 115, 116, 117, 111, 112, Telecom Closet, 114, Custodial, Cafeteria, Lounge, Kitchen, Staff BR, 109, 110/S-22, E3, 203, 215, 227, Prep Room, Telecom Room, Media Production, Wellness Center, E5, S-28/Telecom Closet, 3rd Floor Hall N.E., E8, 325, Telecom 4, 3rd Floor Hall S.W., 301, 303, 333, 335, 337, Stairwell by 337, S-31</p>	<p>Dust and/or overwhelming clutter in all specified areas.</p>	<p>X</p>						
<p>7. No signs of animal infestation</p>	<p>Equip Storage, Instrument Repair, Control Room, Wrestling Storage/N.E. Stairwell, S-31</p>	<p>IPM needed in these areas.</p>	<p>X</p>	<p>X</p>	<p>22053</p>	<p>2/23/2017</p>			
<p>8. Ceiling tiles present; no broken, stained, or painted</p>	<p>100, Instrument Repair, Practice Room, 102 Work Room, Auditorium Hall, Control Room, Planning/106/Wrestling Storage/Wrestling/115, 111, 112, 114, Custodial, Cafeteria, Lounge, Staff BR, 110/ 200, S-23, Hall, S-25, Hall Outside 216, Hall Outside Media, 221, 222/Boys BR by 205, E5, Hall Outside E6/ Storage/ 203, 207, 225, 228/229/Hall Outside 220/208, 208A, Hall Outside 208, 210, Prep Room, Hall Outside Prep Room, Telecom Room, Transition Room, 214, Media Center, Telecom Room Outside Media, 218, 223, 232/N.E. Stairwell, 307, 309, 310, Hall Outside 312, 317, Hall Outside 317, 328, 327, 329B, 331, Hall Outside 329B, 337, 300, Hall Outside E-6/325, CS-8, Planning/308, 311, 322</p>	<p>Stained ceiling tiles/Hole in 106 ceiling tile/Loose ceiling tile in Wrestling Storage/Missing ceiling tile in Wrestling/Stained ceiling tiles/Hole in tile between two lights in 200, S-23, Hall, S-25, Hall Outside 216, Hall Outside Media, 221, and 222/Light Lense needs replacement in Boys BR by 205, E5, and Hall Outside E6/Cracked ceiling tile in Storage/Chipped ceiling tile in 203, 207, 225, and 228/Painted ceiling tiles in 229/Sprinkler head needs replacement in Hall Outside Room 220, 203/Stained ceiling tile/Stained ceiling tiles/Sprinkler head needs replacement in 325, CS-8, 329B, and Planning/Painted ceiling tiles in 308, 311, 322</p>		<p>X</p>	<p>22037</p>	<p>2/23/2017</p>			

IEQ SCHOOL DATA BASE

School Name: Reservoir High School

Principal: Patrick Sauderson

DATE: 1/23/2017

IEQ Team Leader: Adam Downes

IEQ System Leader: Greg Maciulla

9. Walls show no signs of water damage/mildew/ paint irregularities	308, 329A, 330, 337 Closet	Crack in wall in specified room.		X	22039	2/23/2017		
10. No condensation or other evidence of humidity on ceilings, walls, doors, etc.	Instrument Repair, 106/Girl's BR by 205/Prep Room, 308/Science Planning/313 Closet, S-31/310	Ceiling tile leak/Water stained tile/Evidence of a past leak/Ceiling tile leak in Prep Room and 308/Moisture on exterior wall in Science Planning /Active leak in 313 Closet and S-31/Wall leak in 310.		X	22042	2/23/2017		
11. Limited use of non-issued HCPSS furniture and appliances	100, Office, Planning, Malette, Work Room, Babe, Guidance, Bellamy/Finch, Thurmon/Flex Office, 120, 117, Custodial/ 201, S-23, AP Office, 206, Transition Room, E-4, 215, Media Storage, Media Production, 220, 227, 230, 231, 234, S-29, S-30, Wellness Center/Bama, Prep Room, 308, 312 Closet, 313, 314, 318, 320, 321, 321 Closet, 324, R. White, 328, 327, 329A, 333, 300, 301, 302	Non-issued shelving units, microwaves, refrigerators, teapots, coffeemakers, and lights.	X					
12. No excessive fabric materials, stuffed animals, beanbags, pillows, etc.	102/ Athey, Conference, Babe, Special Ed Conference, Dellinger, Guidance, Packman, White/AP Office, 220, 226, 227/314, 315, Staff BR, 317, 319, 320, 321, 325, 326A, 327, 333, Planning, 301	Curtains, rugs, couches, chairs, flags, and stuffed animals in areas need to be removed.	X					
13. No structural or physical gaps around exit doors	328/	Shelving unit blocking doorway.	X					
14. No improperly stored materials/chemicals	S-23, 209, 227, S-30/319, R. White, 321, 326A, 333, Planning Kitchen	Unmarked bottles or unapproved cleaners.	X					
15. Floor coverings are level and secure (tile, carpets, wood board, etc.)	Instrument Repair Room/321	Carpet slightly torn and ripping at the seam.		X	22043	2/23/2017		

IEQ SCHOOL DATA BASE

School Name: Reservoir High School

Principal: Patrick Saunderson

DATE: 1/23/2017

IEQ Team Leader: Adam Downes

IEQ System Leader: Greg Maciulla

40. No stains from roof on outside walls

41. Bins from garbage and recycling clearly marked

42. Hard surfaces (sidewalks, etc.) cleared of any turf application

43. Proper maintenance of planted beds and other vegetation

44. Landscaping and turf look healthy and disease free

COMMENTS: